

HS Clearcoat P390-4000

Description

P390-4000 is a modern, high solids urethane clearcoat for auto refinish. It is specifically designed for use over Value-PRO[™] Basecoat Colors (VB), and may also be used over Value-PRO VU.

Products Clearcoat: P390-4000

Hardener for Clearcoats: P315-3511

Thinner: P830-2065 Fast

P830-2075 Medium P830-2085 Slow P830-2095 Extra Slow P830-2097 Super Slow

Suitable for use over:

Value-PRO VB/VBP Basecoat Allow at least 20 minutes flash time before clearcoat.

Colors.

Value-PRO VU 2 Pack Urethane Allow 30 minutes to 1 hour air dry and no more than 5

Colors. days before clearcoat.

May also be incorporated into the final coat of VU color for improved gloss and durability. Add up to 25% by volume of **ACTIVATED** P390-4000 clearcoat to the final coat of **ACTIVATED** Value-PRO VU color.

Surface Preparation:

Refer to the data sheet for Value-PRO VB / VBP (RM 2610) or VU (RM 2609).

Mixing :

Clearcoat: P390-4000 Hardener: P315-3511

Thinner: P830-20XX

Pot Life:

Ву

volume:4 Parts

1 Part

1 Parts

3 hours

Additives - see datasheet RM 2620

- P300-9002 Accelerator
- P300-9003 Potlife Extender
- P300-9004 Fisheye Preventer
- P300-9005 Flexible Additive
- P300-3199 Matting Agent

Matting Agent P350-3199:

If a low gloss finish is required, add Matting Agent to the clearcoat prior to activating and thinning.

Semi-gloss: Add 50% P350-3199 = 1 part Matting Agent to 2 parts Clearcoat.

Matt: Add 60% P350-3199 = 3 parts Matting Agent to 5 parts Clearcoat.

Activate and thin the above mixtures as normal 4:1:1

Application



Conventional Tip size 1.3 – 1.6 mm

gun: Air pressure 50-60 psi at the gun

Tip size 1.2 – 1.5 mm

HVLP gun: Air pressure 10 psi max at the tip

HVLP: Refer to manufacturer's inlet pressure requirements

Coats



2 coats Flash Time



(2.0-2.5 mils dry film)

5-10 minutes between coats (@ 70°F/21°C)

Drying



Air Dry (@ 70°F/21°C): Dust Free: 60-80 minutes

Tack Free: 2½-3½ hours
Tape Free: 12 hours

Polish / Into Service: 16 hours (overnight)

Force Dry: 30 minutes @ 140°F/60°C

Polish / Into Service: after 2 hours

Infra Red (medium wave) 12-15 minutes

Rectification After "into service" times / air dry or Recoat After 2 hours cool down / force dry

Process Notes

For Value-PRO VB / VBP basecoat, the maximum time to clearcoat is 24 hours. If left longer, scuff thoroughly and apply additional basecoat before applying clearcoat.

For Value-PRO VU 2 Pack Urethane, the maximum time to clearcoat is 5 days. If left longer, scuff thoroughly before applying clearcoat

Clean up equipment immediately after use, using thinner Value-PRO or another suitable solvent. Dispose of waste in accordance with applicable regulations

VOC Package = 4.2 lb/gal, Applied (4:1:1) = 4.3 lb/gal

Coverage 626 sq. ft. / gal, at 1 mil dry film.

See Material Safety Data Sheet and Labels for additional safety information and handling instructions

EMERGENCY MEDICAL OR SPILL CONTROL INFORMATION:

USA (412) 434-4515; CANADA (514) 645-1320; MEXICO 91-800-00-214